


CORNER RECORD

Document Number 130805.102

City of UNINCORPORATED

County of Amador, California

Brief Legal Description Pt N NE 1/4 of Sec 5 T13N R3E M DM



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey _____

COORDINATES (Optional)

- N. _____
- E. _____
- Zone _____ NAD27 NAD83
- NAD83 Epoch _____
- Elev. _____
- Vert. Datum: NGVD29 NAVD88
- Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Find Mon 4's per 4-RS-94
Reset missing curbs as shown


A description of the physical condition of the monument as found and as set or reset:

Reset missing curbs w/ 3/4" REBAR w/ PLASTIC CAP
STAMPED R/E 29265

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 7-7-08

Signed R.G. Hillman P.L.S. or R.C.E. No. RCE 29265
EXP 3-31-09



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 27, 2008

and examined and filed September 15, 2008

Signed Thomas P. Martin P.L.S. or R.C.E. No. 5618

Title County Surveyor

County Surveyor's Comment _____



PARCEL 1
17-PM-07



SET 3/4" REBAR
RCE 29265

N77°58'W

285.73'

FND.
1" SQ BOLT

RS 4-94

N02°48'15"W 150.33'

128.51'
177.88'

SET 3/4"
REBAR
RCE 29265

N80°31'W 200.88'

SET 3/4" REBAR
RCE 29265

NORTH

FND 3/4"
REBAR
LS
3014

NORTH 85.00'

S67°26'W 80.29'