


**COUNTY OF NEVADA
CORNER RECORD**

Document Number 140823.112

City of UNINCORPORATED County of Nevada, California

Brief Legal Description Pt SW 1/4 SEC. 23 T14N R8E M.D.M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 3-30-12

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FND. 3/4" IRON PIPE LS 4370 @ SIX CORNERS ALONG THE
 LINE COMMON TO PCL 1 AND PCL 2 19-PM-197. RESET
 MISSING CORNER @ S. END OF COMMON LINE

A description of the physical condition of the monument as found and as set or reset:

RESET MISSING CORNER w/ 3/4" REBAR w/ PLASTIC CAP
 STAMPED RLB 29265

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 4-8-12

Signed R G Hillman P.L.S or R.C.E. No. RLB 29265



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 12, 2012


and examined and filed APRIL 30, 2012

Signed Kevin J. Nelson P.L.S or R.C.E. No. 8423

Title COUNTY SURVEYOR



County Surveyor's Comment _____



- FND 3/4" IRON PIPE LS 4370
- RESET MISSING MONT W/ 3/4" REBAR LS 29265

