


**CORNER RECORD**

Document Number 140832.101

City of \_\_\_\_\_

County of NEVADA, California

Brief Legal Description Plns Sec 32 133 T14N R8E AND SEC 415 T13N R8E M.D.M. LOTA G. HUBBY/LS



**CORNER TYPE**

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey 5-1-06

**COORDINATES (Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29  NAVD88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FIND. MON'TS 3/4" IRON PINS w/ PLASTIC CAPS LS 3847 OR LS 4227


A description of the physical condition of the monument as found and as set or reset:

RESET MISSING CAPS w/ 3/4" REBAR w/ PLASTIC CAP STAMPED RLE 29265

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 5-7-06

Signed R.G. Hillman P.L.S or R.C.E. No. RLE 29265




**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received June 14, 2006

and examined and filed June 19, 2006

Signed Thomas P. Martin P.L.S or R.C.E. No. 5618

Title Deputy County Surveyor



County Surveyor's Comment \_\_\_\_\_

- FND. MON'T PER 6-SUBDV-15
- RESET MISSING MON'T W/  
3/4" REBAR W/ PLASTIC CAP  
STAMPED RCE 29265

