

**CORNER RECORD**

Document Number 140827.120

City of LAKE OF THE PINES County of Nevada \_\_\_\_\_, California

Brief Legal Description PTA SECTION 27 T14N R8E M.17.B.1M



**CORNER TYPE**

**COORDINATES (Optional)**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
FND 3/4" IRON PIPE @ NW COR LOT 147 & S. COR LOT 149 & SW COR LOT 146, FND 3/4" REBAR W/ WIRES FOR TAG BUT TAG IS MISSING. USED THESE POINTS TO RESET MISSING CORNERS ON NORTHERLY LINE LOT 146

A description of the physical condition of the monument as found and as set or reset:  
SET 3/4" REBAR W/ PLASTIC CAP STAMPED RLB 29265


**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MARCH 27 192000  
Signed R. G. Hillman L.S. or R.C.E. Number RLB 29265



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received April 7, 2000 and examined  
and filed April 10, 2000  
Signed Thomas P. Martin Title Deputy County Surveyor



County Surveyor's Comment \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

