


CORNER RECORD

Document Number 140827.122

City of UNINCORPORATED County of Nevada _____, California

Brief Legal Description PTN 5E1/2 SEC 27 T14N R8E - LOT 1384 2-509-95



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 6-6-00

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENTS SHOWN MARKED W/ 3/4" IRON PIPE. TYPICAL OF THOSE USED IN LAKE OF THE PINES. USED MONUMENTS SHOWN TO RE-ESTABLISH MISSING CORNERS

A description of the physical condition of the monument as found and as set or reset: SET 3/4" REBAR W/ PLASTIC CAP STAMPED RLB 29265 AT MISSING CORNERS

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 28 192000

Signed R B Hellman L.S. or R.C.E. Number RLB 29265



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received July 31, 2000 19 and examined and filed August 8, 2000 19 .

Signed Thomas P. Martin Title Deputy County Surveyor



County Surveyor's Comment _____

- FND. 3/4" IRON PIPE
- SET 3/4" FCBAR W/ PLASTIC CAP STAMPED RCE 29265

