

**CORNER RECORD**

Document Number 1A0827.136

City of UNINCORPORATED

County of Amador, California

Brief Legal Description R4N 5W 1/4 Sec 22 E NW 1/4 Sec 27 T14N R6E MDM Lot 8 2-90084



**CORNER TYPE**

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey 7-7-08

**COORDINATES (Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29  NAVD88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND BC ON TORREY PINES ROW AND NE COR MON'T TO  
CALCULATE POSITIONS OF MISSING CORNERS. END 3/4"  
IRON PIPE OF TYPE USED IN LAGE OF THE PINES


A description of the physical condition of the monument as found and as set or reset:

RESET MISSING MON'TS w/ 3/4" REDBAR w/ PLASTIC CAP STAMPED  
RCE 29765

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyor's Act on 7-10-08

Signed R.G. Hillman P.L.S or R.C.E. No. RCE 29765



**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received July 18, 2008

and examined and filed July 24, 2008

Signed Thomas P. Martin P.L.S or R.C.E. No. 5618

Title County Surveyor

County Surveyor's Comment \_\_\_\_\_



SYCAMORE CT.

R=270' Δ=121°18'29" Q=58.00' N87°06'E  
22.00'

LOT 8  
WESTERN LAKE PROPERTIES  
UNIT 1A  
2-SUB-84

N01°53'27"E 182.30'

S02°54'E 193.26'

N80°35'W 62.02'

R=210'  
Δ=09°25'16" Q=34.53'

TORREY PINES DRIVE



- FND 3/4" IRON PIPE PER 2-SUB-84
- RESET MISSING CNR. W/ 3/4" REBAR W/ PLASTIC CAP STMPD. RCE 29265
- NOTHING FND. OR SET

