


CORNER RECORD

Document Number 1408 27. 137

City of _____ County of Nevada _____, California

Brief Legal Description Lot No. 1401 Western Lake Properties Unit No. 2B



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Reset the southeast corner and the south angle point corner on the south line
of the Boxer & BuBord property, as shown on Record of Survey No. IA 93-017
recorded in Book 11 of Surveys at Page 98, Nevada County Records, as per
the diagram on the reverse side of this page.


A description of the physical condition of the monument as found and as set or reset: _____

See reverse side

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on May 18, 2009 19__.

Signed [Signature] L.S. or R.C.E. Number LS 4415
 Exp. 09/30/09



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 8, 2009 19__ and examined
 and filed June 9, 2009 19__.

Signed [Signature] Title County Surveyor

County Surveyor's Comment This survey is located in
T. 14 N., R. 8 E., MDM.



Scale 1"=40'

