


COUNTY OF NEVADA
CORNER RECORD

Document Number 140826.129

City of _____

County of Nevada, California

Brief Legal Description LOT 937 & 938 WESTERN LAKE PROPERTIES UNIT 2-A



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey FEB 1, 2001

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

● INDICATES FOUND 3/4" IRON PIPE PER WESTERN LAKE PROPERTIES UNIT 2-A, RECORDED IN BOOK 2 SUBS PG 89, NEVADA COUNTY RECORDS

A description of the physical condition of the monument as found and as set or reset:

Q INDICATES 5/8" REBAR SET, TAGGED RCE 13845

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyer's Act on OCT 18, 2002

Signed _____ P.L.S. or R.C.E. No. 13845



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 21, 2002

and examined and filed November 20, 2002

Signed Thomas P. Martin P.L.S. or R.C.E. No. 5618

Title Deputy County Surveyor

County Surveyor's Comment This property is in Section 26, T. 14 N., R. 8 E.

