


CORNER RECORD

Document Number 140827.134

City of _____ County of Nevada _____, California

Brief Legal Description Lot 249 Western Lake Properties Unit 1A Bk 2 Subs Pg 84



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 12/08/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Restablished the northwest and southeast corners of Lot 249
from found evidence of remaining corners as shown on detail on
page 2.

A description of the physical condition of the monument as found and as set or reset: _____
See attached detail on page 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 10, 2003 ~~19XX~~.

Signed [Signature] L.S. or R.C.E. Number L.S. 4415



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received December 10, 2003 19__ and examined and filed January 7, 2004 19__.

Signed [Signature] Title Deputy County Surveyor

County Surveyor's Comment _____



LAKE OF THE PINES



FOUND PENNY TAG (UNREARABLE)
AFFIXED TO ROCK FACE
BELOW WATER SURFACE

CHISELED 'X' IN TOP
OF ROCK, IN MORTAR WALL

S 68°31'33" E
55.43'

S 41°35'12" E
45.62'

FOUND 3/4" IRON PIPE
TAGGED ROE #199 AT END
OF ROCK MORTAR WALL

SUBS
LOT 248
LOT 249
LOT 250

N 19°35'20" E 290.43'

S 29°08'12" W 275.85'

FOUND 3/4" IRON PIPE
NO TAG

SET 5/8" REBAR
MODELS LS 4415

DELTA 12°27'42"
R 230.00'
L 50.00'

LAKE SHORE JUDY